


**INSTALLATION INSTRUCTIONS**  
**for the**  
**PLENUM**  
**on the**  
***Kodak M35/M35A/M35A-M/M35-M X-Omat* PROCESSOR**  
**Service Code: 3041, 3047, 3133, 3408**  
***Kodak Professional Industrex M35/M35A* PROCESSOR**  
**Service Code: 3414, 3296**  
***Kodak Professional Industrex M35I/M35I-M* PROCESSOR**  
**Service Code: 3415, 3400**  
***Kodak X-Omat 2000/2000A* PROCESSOR**  
**Service Code: 3554, 3555**  
***Kodak Min-R* MAMMOGRAPHY PROCESSOR**  
**Service Code: 3752**



---


**PLEASE NOTE** The information contained herein is based on the experience and knowledge relating to the subject matter gained by Eastman Kodak Company prior to publication.

No patent license is granted by this information.

Eastman Kodak Company reserves the right to change this information without notice, and makes no warranty, express or implied, with respect to this information. Kodak shall not be liable for any loss or damage, including consequential or special damages, resulting from any use of this information, even if loss or damage is caused by Kodak's negligence or other fault.



This equipment includes parts and assemblies sensitive to damage from electrostatic discharge. Use caution to prevent damage during all service procedures.



### Warning

Dangerous Voltage

- [1] De-energize the PROCESSOR.
- [2] Does the existing DRYER RACK AY have a GASKET on the bottom of the PLENUM?

Yes	No
<ol style="list-style-type: none"> <li>1. Remove and discard the existing PLENUM and GASKET.</li> <li>2. Place the new GASKET on the new PLENUM.</li> <li>3. Install the new PLENUM.</li> </ol>	<ol style="list-style-type: none"> <li>1. Check that a GASKET is installed on the FRAME. <ul style="list-style-type: none"> <li>• If a GASKET is installed on the FRAME, it is not necessary to install the new GASKET. Keep the new GASKET for future use.</li> <li>• If a GASKET is not installed on the FRAME, install the new GASKET on the new PLENUM.</li> </ul> </li> <li>2. Install the new PLENUM.</li> </ol>



### Note

You should have only one GASKET installed on the equipment.

- [3] Energize the PROCESSOR.
- [4] Check that the PROCESSOR is operating correctly.

## Publication History

Print Date	Pub. No.	ECO No.	Affected Pages	File Name	Notes
20APR00	6E7656	- - -	All	ii3041_3_20apr00.fm	New Publication

*Kodak, Industrex, Kodak Professional, Min-R, and X-Omat are trademarks.*